



# Vehicle Inspection Checklist

Robbie White / Jason Reyes / 21 Jun 2023

**Complete**

Score	<b>92.31%</b>	Flagged items	<b>0</b>	Actions	<b>0</b>
<b>Client / Site</b>	Robbie White				
<b>Location</b>	8068 Ortigas Ave Ext, Cainta, Rizal, Philippines				
<b>Prepared by</b>	Jason Reyes				
<b>Conducted on</b>	21.06.2023 12:30 PST				

Audit

92.31%

## General Information

Select vehicle identification type

VIN

License Plate #

Other

Enter VIN #

5F08A2257591

Enter License Plate No.

IK 2845

Take photo of license plate



Photo 1

Enter identification type

Ford Everest 2015 Dark Blue

Enter Mileage

91,308

Take photo of vehicle



Photo 2

## Inspection

92.31%

### BRAKE SYSTEM

100%

Service brakes

OK

Parking brakes

OK

Brake drums/rotors

Not Applicable

Brake hose

OK

Low pressure warning device

OK

## COUPLING DEVICES

<b>Fifth wheel</b>	Not Applicable
<b>Pintle hooks</b>	Not Applicable
<b>Drawbar/towbar eye and tongue</b>	Not Applicable

## ENGINE OPERATION

75%

<b>Fan/compressor belts</b>	OK
<b>Oil pressure</b>	OK
<b>Radiator</b>	OK
<b>Battery</b>	Needs Repair

Car battery became more pronounced. Colder temperatures made the engine oil much thicker.



Photo 3

REFERENCE: Vehicle Battery clean and maintained regularly  
 [This is an example of how you can use iAuditor to include best practice reference images in your templates to assist with inspections]



## EXHAUST SYSTEM

100%

<b>Check below driver position</b>	OK
<b>Check for damage to wiring and fuel line</b>	OK
<b>Muffler</b>	OK

## FUEL SYSTEM

66.67%

### Visible leak

Needs Repair

Leaks found on fuel engine system.



Photo 4

### Fuel tank filler cap missing

OK

### Fuel tank securely attached

OK

## LIGHTING DEVICES

100%

### Head lights

OK

### Brake lights

OK

### Tail lights

OK

### Dash lights

OK

### Clearance lights

OK

### Turn indicators

OK

## SAFETY EQUIPMENT

100%

### Seat belts available and working

OK

### Fire extinguisher

Not Applicable

### Fags, flares

OK

### Decals

OK

### Spare bulbs, fuses

OK

## SAFE LOADING

100%

### Protection against shifting cargo

OK

### Lift gate and accessories

OK

## STEERING MECHANISM

87.5%

Steering wheel free play	OK
Steering column	OK
Front axle beam	OK
Steering gear box	OK
Pitman arm	Needs Repair

Noticed some steering problems due to poor condition of pitman arm.



Photo 5

Power steering	OK
Ball and socket joints	OK
Tie rods, drag links	OK

## SUSPENSION

100%

U-bolts and spring hangers	OK
Spring assembly	OK
Tongue, radius or tracking components	OK

## TIRES

100%

Condition	OK
Air pressure	OK
Chains	OK

## WHEELS

75%

Wheels and rims	OK
Lock or side rings	Needs Repair

Side rings are dirty.



Photo 6

<b>Fasteners</b>	OK
<b>Welds</b>	OK
<b>WINDSHIELD</b>	100%
<b>Glass free of cracks, discoloration</b>	OK
<b>Wiper power unit, blades</b>	OK
<b>MISCELLANEOUS</b>	100%
<b>Transmission fluid</b>	OK
<b>Clutch free play</b>	OK
<b>Heater/defroster</b>	OK
<b>Mirrors</b>	OK
<b>Frame</b>	OK
<b>Body</b>	OK

## SUMMARY

**List any other conditions which may prevent safe operation of this vehicle**

1. Watch for leaks
2. Regular maintenance
3. Gas cap required

**Enter any other observations**

None

**Rate the overall condition of the vehicle**

Average

## Recommendations

**Enter recommendations here**

1. Regularly check the vehicle components.

2. Check for leaks.
  3. Inspect tire pressures.
  4. Be mindful of the steering system.
  5. Clean the brake dust off of the wheels.
  6. Check oil levels.
- 

## COMPLETION

---

### Full Name and Signature of Inspector



Jason Reyes  
21.06.2023 12:59 PST

---

## Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6