



Visual Inspection Report Form

1 Feb 2023 / Samantha Leibnitz / Welding

Complete

Flagged items

2

Site conducted

Unanswered

Company

Steelix Manufacturing Ltd.

Department

Welding

Address

3428 Hillcrest Lane, Primmer
CA

Prepared by

Samantha Leibnitz

Conducted on

01.02.2023 10:00 PST

Flagged items

2 flagged

Inspection / Visual Inspection Report Form / Part / Part 3

Defect Criteria

Fail

Inspection / Visual Inspection Report Form / Part / Part 5

Defect Criteria

Fail

Inspection

2 flagged

Visual Inspection Report Form

2 flagged

Part

2 flagged

Part 1

ID & Location

01 / AE03

Take/attach photos




Photo 1

Defect Criteria

Pass

Part 2

ID & Location

02 / AE03

Take/attach photos



Photo 2

Defect Criteria

Pass

Part 3

1 flagged

ID & Location

03 / AE03

Take/attach photos



Photo 3

Defect Criteria

Fail

Identify visual defect/s.

Incomplete fusion

Arc strikes

Part 4

ID & Location

04 / AE03

Take/attach photos



Photo 4

Defect Criteria

Pass

Part 5

1 flagged

ID & Location

05 / AE03

Take/attach photos



Photo 5

Defect Criteria

Fail

Identify visual defect/s.

Burn through

Under cut

Part 6

ID & Location

06 / AE03

Take/attach photos



Photo 6

Defect Criteria

Pass

Completion

Additional Observations

We should keep on using SafetyCulture for our visual inspections to easily identify visual defects!

Quality Assurance Inspector Name & Signature

Samantha Leibnitz
09.02.2023 14:08 PST

Appendix



Photo 1



Photo 2



Photo 3



Photo 4




Photo 5



Photo 6