

Name

ID

# **Driver Vehicle Inspection Report (DVIR) Form**

8 Mar 2024 / Alice Johnson Complete Score 0 / 0 (0%) **Flagged items Actions** 2 **Company Name RJH** Logistics **Conducted on** 08.03.2024 09:00 PST **Prepared by** Alice Johnson Los Angeles, CA, USA (34.0549076, -118.242643) Location Vehicle Information ID V12345 Make Freightliner Model Cascadia 2022 Year **License Plate** XYZ 123 **Driver Information** 

Jill Wreight

D56789

## Flagged items & Actions

1 flagged, 2 actions

Flagged items

1 flagged, 1 action

Report / Post-Trip Inspection

### **Brake fluid level**





Photo 1

**To do** | Assignee: SafetyCulture Staff | Priority: Low | Due: 04.03.2024 19:30 PST | Created by: SafetyCulture Staff

Minor leak detected in brake lines. For repair.

Other actions 1 action

Report

### **Defects and Issues (if any)**

Minor leak detected in brake lines during post-trip. Action created and to be taken: Marked for repair.

**To do** | Assignee: SafetyCulture Staff | Priority: Low | Due: 04.03.2024 18:00 PST | Created by: SafetyCulture Staff

Endorse repair work to crew.

Report	1 flagged, 2 actions
Pre-Trip Inspection	
Time of Pre-Trip Inspection	08.03.2024 09:00 PST
Brake fluid level	Safe
Brake pedal resistance	Safe
Brake lines and hoses	Safe
Headlights (high and low beam)	Safe
Brake lights	Safe
Turn signals	Safe
Tread depth	Safe
Tire pressure	Safe
Spare tire condition	Not Applicable
No spare tire available.	
Steering wheel play	Safe
Power steering fluid level	Safe
Tie rods and drag link	Safe
Shocks and struts	Safe
Leaf springs	Safe
Bushings and mounts	Safe
Windshield wipers	Safe
Horn	Safe
Mirrors	Safe
Post-Trip Inspection	1 flagged, 1 action
Time of Post-Trip Inspection	08.03.2024 17:30 PST

Brake fluid level At Risk



Photo 1

**To do** | Assignee: SafetyCulture Staff | Priority: Low | Due: 04.03.2024 19:30 PST | Created by: SafetyCulture Staff

Minor leak detected in brake lines. For repair.

Brake pedal resistance	Safe
Brake lines and hoses	Safe
Headlights (high and low beam)	Safe
Brake lights	Safe
Turn signals	Safe
Tread depth	Safe
Tire pressure	Safe
Spare tire condition	Not Applicable
No spare tire available.	
Steering wheel play	Safe
Power steering fluid level	Safe
Tie rods and drag link	Safe
Shocks and struts	Safe
Leaf springs	Safe
Bushings and mounts	Safe
Windshield wipers	Safe
Horn	Safe
Mirrors	Safe

# Defects and Issues (if any)

Minor leak detected in brake lines during post-trip. Action created and to be taken: Marked for repair.

**To do** | Assignee: SafetyCulture Staff | Priority: Low | Due: 04.03.2024 18:00 PST | Created by: SafetyCulture Staff

Endorse repair work to crew.

### Completion

#### **Comments or Additional Notes**

- During the pre-trip inspection, a minor leak was detected in the brake lines, and it has been marked for immediate repair.
- The spare tire is not present, which is noted as "Not Applicable" in both the pre-trip and post-trip inspections.
- All lights, including headlights, brake lights, and turn signals, are functioning properly.
- Tread depth and tire pressure are within acceptable ranges.
- No abnormalities were observed in the steering components, including steering wheel play, power steering fluid level, tie rods, and drag link.
- Shocks, struts, leaf springs, bushings, and mounts are all in good condition.
- Windshield wipers are operational, and the horn is functioning as expected.
- Mirrors show no signs of damage or misalignment.

#### **Driver's Signature**

Jill Wreight 08.03.2024 20:28 PST

Mechanic's Signature (if applicable)

Isaac Kepler 08.03.2024 20:29 PST

# Media summary



Photo 1