



Incident Report - First Response

Complete

Score	1 / 6 (16.67%)	Flagged items	0	Actions	1
Document No.					02812209-IR
Audit Title					Electrical Hazard Incident Report
Client / Site / Project					Electrical System Maintenance and Repair - 2nd floor, RDJ Commercial Spaces, Inc.
Report conducted on					22 Sep 2023 13:00 PST
Prepared by					Jake Cobb - Team Lead
Location					Los Angeles, CA, USA (34.0549076, -118.242643)

Actions

1 action

Audit / Corrective Actions

Are corrective/further actions required with regard to this incident?

Yes

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 29 Sep 2023 14:23 PST | Created by: SafetyCulture Staff

Inspect all labels on electrical panels to avoid workers' direct contact with hazardous systems.

Audit	1 action, 1 / 6 (16.67%)		
First Incident Details	-2 / 3 (0%)		
Date & Time of Incident	22 Sep 2023 12:30 PST		
Location of Incident	Los Angeles, CA, USA (34.0549076, -118.242643)		
Incident Priority?	High		
Site / Project Name	Electrical System Maintenance and Repair - 2nd floor, RDJ Commercial Spaces, Inc.		
Incident Type?	<table border="1"> <tr> <td>Hazard</td> <td>Injury</td> </tr> </table>	Hazard	Injury
Hazard	Injury		
Name of on-duty supervisor at time of incident?	Hailey Park		
Is immediate medical attention required?	Yes		
What kind of medical attention was administered?	<table border="1"> <tr> <td>First Aid</td> <td>Hospital</td> </tr> </table>	First Aid	Hospital
First Aid	Hospital		
Describe What Happened			
<p>Describe what happened. Please be detailed but state only facts.</p> <p>On the afternoon of September 22, 2023, at approximately 12:30 PM, a critical incident occurred involving one of our electrical system workers, Mr. John Turner, while he was performing routine maintenance on an electrical panel at a commercial client's premises.</p> <p>The incident took place at Industrial Avenue, Los Angeles, CA during a scheduled maintenance visit. Mr. Turner was assigned to inspect and troubleshoot an electrical panel supplying power to various machinery in the client's manufacturing facility. While conducting his work, Mr. Turner identified a potential issue with one of the circuit breakers that required immediate attention.</p> <p>Upon opening the electrical panel and attempting to perform a visual inspection, Mr. Turner inadvertently made contact with a live wire due to inadequate labeling and a lack of clear identification of the circuit breaker in question. This resulted in an electrical shock, causing Mr. Turner to sustain injuries.</p>			
What were the weather / environmental conditions at the time of the incident?	Clear		
Record Evidence and Information			
Which of the following do you need to attach to this report to accurately document this incident?	Evidence		

Evidence Log

Please log all relevant evidence below

Evidence

Evidence 1

Evidence Description

A photo of the live wire that John Turner was exposed to

Evidence ID number (if applicable)

EV-EIR-01

Type of evidence

Photos

Photos of evidence (if applicable)




Photo 1

Please detail any further information regarding this evidence (if applicable)

N/A

People involved

2 / 2 (100%)

Please document all people involved in this incident, including yourself (the person reporting the incident)

Person

2 / 2 (100%)

Person 1

1 / 1 (100%)

Person

1 / 1 (100%)

Full Name

Jake Cobb

ID number

EWI-05543

Contact phone number

What is this person's relation to the incident? (select all that apply)

Reporter of incident

Witness

Please describe this person's involvement with the incident, including all relevant information

I was with John Turner on the 2nd floor during the electrical work. I happened to hear something bad, and then I witnessed the incident first-hand.

Does this person wish to make a preliminary statement?

No

Has this person sustained an injury?

No

Person 2

1 / 1 (100%)

Person

1 / 1 (100%)

Full Name

Hailey Park

ID number

EWI-02443

Contact phone number

213-637-1092

What is this person's relation to the incident? (select all that apply)

On-duty supervisor

Please describe this person's involvement with the incident, including all relevant information

I promptly reported the incident to the on-duty supervisor.

Does this person wish to make a preliminary statement?

No

Has this person sustained an injury?

No

Corrective Actions

1 action, 1 / 1 (100%)

Are corrective/further actions required with regard to this incident?

Yes

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 29 Sep 2023 14:23 PST | Created by: SafetyCulture Staff

Inspect all labels on electrical panels to avoid workers' direct contact with hazardous systems.

Have all required corrective actions been added as Actions to this inspection?

Yes

Please add any corrective actions to the appropriate questions above before completing this incident report

Sign Off


Further action/follow-up/investigation required?

Yes

Name of person/people to follow up

Kent Paige - for the inspection of electrical panel labels due next Thursday

Name & Signature of Reporter



Jake Cobb - Team Lead
22 Sep 2023 14:34 PST

Media summary




Photo 1