



Drainage Inspection Checklist

Mines Inc. / 23 Jun 2023 / Kev Roms

Complete

Score	100%	Flagged items	0	Actions	1
Client / Site					Mines Inc.
Personnel					Kev Roms
Date and Time of Inspection					23.06.2023 16:55 PST
Location					168 Little Collins St, Melbourne VIC 3000, Australia (-37.8138421, 144.9680228)

Actions

1 action

Location Details / Nature of Incident

Content of blockage

Sanitary products



Photo 1

To Do | Assignee SafetyCulture Staff | Priority High | Due 30.06.2023 16:57 PST | Created by SafetyCulture Staff

Share reminders about sanitary protocol to all employees.

Hi Karen, please send an email to remind all employees on sanitary protocol.

Location Details

1 action, 100%

General Information

100%

Drainage area

Inside Property

Drain Ownership

Private

Pipe length

11 meters

Pipe size

3 meters

Distance to blockage from the manhole

5 meters

Is this a recurrence of an incident?

No

Nature of Incident

1 action

Consequence of problem

Blockage

Content of blockage

Sanitary products



Photo 1

To Do | Assignee SafetyCulture Staff | Priority High | Due 30.06.2023 16:57 PST | Created by SafetyCulture Staff

Share reminders about sanitary protocol to all employees.

Hi Karen, please send an email to remind all employees on sanitary protocol.

Structural Causes

Interceptor Trap

Work Undertaken

100%

Action Taken

Rodded

Outcome Of Work

Drain Unblocked

Further Action Required

No

Flow of wastewater is back to normal

Completion

Recommendations

- If you experience slow water drain, contact your facilities team to re-investigate the problem.
 - This incident is due to toilet blockage. Please remind all staff regarding sanitary protocol. "Do not flush napkins, toilet paper, or any non-biodegradable materials to toilet bowl".
-

Personnel (Full Name and Signature)



Kev Roms
23.06.2023 16:58 PST

Media summary



Photo 1