

# **Plant Risk Assessment Template**

Smelting Ores / 9 Jun 20	)23 / John	ST			Complete
Score	62.5%	Flagged items	0	Actions	0
Site name					Smelting Ores
<b>Conducted on</b> 09.06.2023 15			09.06.2023 15:30 PST		
Prepared by			John S T		
Location				Phillips	Run Rd, Summersville, WV 26651, USA

Plant Risk Assessment 62.5%

### **Plant Information**

100%

#### **Plant Item**

Foundry casting

#### Plant Identification Details (Model/ Make/ Serial)

GOT1442019

#### **Plant Owner Name**

Dany T. T.

#### Plant task description

Use of foundry casting at new facility

Is the plant designed to perform the task?

Yes

Is the plant in good working condition and free of weeds and mud?

Yes

#### References

Risk Matrix Reference

# **Risk Matrix**

Likelih	ood	Very Likely	Likely	Unlikely	Highly Unlikely
	Fatality	High	High	High	Medium
Consequences	Major Injuries	High	High	Medium	Medium
Conseq	Minor Injuries	High	Medium	Medium	Low
	Negligible Injuries	Medium	Medium	Low	Low



### **Explosion/Fire**

0%

Can anyone be injured by an explosion of gas, vapours, liquids, dusts or other substances, triggered by plant operation?

Yes

#### Hazard

#### **Activity**

Monitoring metal casting

#### **Description of hazards identified**

molten metal, and sparks

#### **Photo of hazard (optional)**



Photo 1

#### Persons at risk

Supervisor

### **Initial risk rating**

Initial consequence	Fatality
Initial likelihood	Likely
Initial risk rating	Medium

### **Residual risk rating**

Residual consequence	Minor Injuries
Residual likelihood	Highly Unlikely
Residual risk rating	Low

#### **Controls**

Select control measures	Engineering Controls
	PPE

### **Enter description of control measures**

Increase distance from viewing desk and proper use of PPE.

Suffocation 0%

Can anyone be suffocated due to lack of oxygen or atmospheric contamination?	Yes
•	

### Hazard

#### **Activity**

Smelting

#### **Description of hazards identified**

Fumes from smelting activity

### Photo of hazard (optional)

#### Persons at risk

All workers on production floor

### **Initial risk rating**

Initial consequence	Major Injuries	
Initial likelihood	Unlikely	
Initial risk rating	Medium	
	Wedluff	
Residual risk rating		
Residual consequence	Negligible Injuries	
Residual likelihood	Highly Unlikely	
Residual risk rating	Low	
Controls		
Select control measures	Elimination	
Enter description of control measures		
Improved ventilation by increasing capacity of exhaust		
Pressurized Content	100%	
Can anyone be injured by fluids or gases under high pressure due to plant failure or misuse?	No	
Electricity Contact	0%	
Can anyone be injured by electrical shock or burnt due to damaged or poorly maintained leads, switches or equipment?	Yes	
Hazard		
Activity		
Use of controls		
Description of hazards identified		
Exposed wires		

# Photo of hazard (optional)



Photo 2

#### Persons at risk

Macrime operator	
Initial risk rating	
Initial consequence	Minor Injuries
Initial likelihood	
Initial risk rating	Medium
Residual risk rating	
Residual consequence	Negligible Injuries
Residual likelihood	Highly Unlikely
Residual risk rating	Low
Controls	
Select control measures	Substitution
	PPE
Enter description of control measures	
Replaced the wiring and constant use of PPE	
Cutting	100%
Can anyone be cut, stabbed or punctured by coming in contact with moving plant or parts?	No
Crushing	100%
Can anyone be crushed due to falling, uncontrolled or unexpected movement of plant or its load?	No
Entanglement	100%
Can anyone's hair, clothing, gloves, necktie, jewellery, rags and other materials become entangled with moving parts of plant, or materials in motion?	No
Slips, Trips, Falls	0%

Can anyone slip, trip, or fall due to: • uneven, slippery, or steep surfaces, Yes obstacles or poor housekeeping • ladders, stairs, platforms, or lack of guardrails Hazard **Activity** Going to the second floor via east entrance **Description of hazards identified** Missing railing **Photo of hazard (optional)** Persons at risk All employees **Initial risk rating Initial consequence Major Injuries** Initial likelihood **Initial risk rating** Residual risk rating **Residual consequence Negligible Injuries** Residual likelihood Highly Unlikely **Residual risk rating** Low **Controls Select control measures** Elimination **Enter description of control measures** 

Can anyone be injured due to poorly designed work area, repetitive body movement, poor light placing, or other ergonomic issues?	No

Installed the railing

**Ergonomics** 

100%

Radiation 100%

Can anyone in the plant's vicinity suffer injury or illness due to exposure to radiation in the form of infra-red, ultra violet light, or microwaves?

No

Noise 0%

Can anyone in the plant's vicinity suffer injury or illness due to exposure to noise?

Yes

#### Hazard

#### **Activity**

Working within the facility

### **Description of hazards identified**

Noise at the facility

#### **Photo of hazard (optional)**

#### Persons at risk

Employees at production floor

### **Initial risk rating**

Initial consequence	Major Injuries	
Initial likelihood	Very Likely	
Initial risk rating	Medium	

### **Residual risk rating**

Residual consequence	Negligible Injuries
Residual likelihood	Highly Unlikely
Residual risk rating	Low

#### **Controls**

Select control measures	Administrative Controls
	PPE

#### **Enter description of control measures**

Admin staff are required to request for access if need to go to production floor. All employees cannot enter the production floor if not wearing PPE.

Vibration 0%

Can anyone in the plant's vicinity suffer injury or ill-health due to exposure to vibration?

Yes

#### Hazard

#### **Activity**

Working near molten metal

#### **Description of hazards identified**

Heat from the molten metal

#### **Photo of hazard (optional)**



Photo 3

#### Persons at risk

All employees at production floor

### **Initial risk rating**

Initial consequence	Minor Injuries
Initial likelihood	Unlikely
Initial risk rating	Medium

### **Residual risk rating**

Residual consequence	Negligible Injuries
Residual likelihood	Highly Unlikely
Residual risk rating	Low

#### **Controls**

**Administrative Controls** 

#### **Enter description of control measures**

Training to reinforce proper distance from molten metals

# Temperature/Moisture

100%

Can anyone be injured or suffer ill-health due to exposure to:

- high or low temperatures
- objects of high or low temperatures
- moisture

No

Other Risks

Other risks that can cause injury or ill-health?

No

# Completion

#### **Recommendations**

Continue to reinforce safety practices through trainings and visible signs.

#### **Name and Signature**

S

John S. T. 09.06.2023 15:52 PST

# Media summary



Photo 1



Photo 3



Photo 2