



School Bus Pre-trip Inspection Checklist

DLS University / ABC 42516 / 26 Apr 2023

Complete

Score	88.37%	Flagged items	5	Actions	3
Site	DLS University				
Bus Number	ABC 42516				
Mileage	1000				
Conducted on (Date and Time)	26.04.2023 13:00 PST				
Inspected by (Full Name)	Joanne Ybell				
Location	Pinehouse, SK S0J 2B0, Canada				

Flagged items & Actions

5 flagged, 3 actions

Flagged items

5 flagged, 3 actions

Inspection / UNDER HOOD

Coolant Level

At Risk

Coolant is below its normal level..

To Do | Assignee SafetyCulture Staff | Priority Low | Due 03.05.2023 13:09 PST | Created by SafetyCulture Staff

Hi Matt, I'll be needing 1L of coolant. Can you bring it...

Inspection / WALK AROUND

Tires and Wheel Lugs

At Risk

Flat tire. Needs replacement.



Photo 1

Inspection / INTERIOR/PRE-IGNITION

Fire Extinguisher

At Risk

Missing fire extinguisher

To Do | Assignee SafetyCulture Staff | Priority Low | Due 03.05.2023 13:11 PST | Created by SafetyCulture Staff

Hi Jack, we have a missing fire extinguisher. Please replace.

Inspection / START ENGINE

Headlights-Dimmer-Hi/ Lo

At Risk

Busted right headlight.

To Do | Assignee SafetyCulture Staff | Priority Low | Due 03.05.2023 13:12 PST | Created by SafetyCulture Staff

Hi Joe, please replace busted lights

Inspection / START ENGINE

Coolant Added (qts)

At Risk

added 1.5 qts

Other actions

0 actions

Inspection

5 flagged, 3 actions, 88.37%

UNDER HOOD

1 flagged, 1 action, 83.33%

Hoses and Belts

OK

Oil Level

OK

Wires

OK

Coolant Level

At Risk

Coolant is below its normal level..

To Do | Assignee SafetyCulture Staff | Priority Low | Due 03.05.2023 13:09 PST | Created by SafetyCulture Staff

Hi Matt, I'll be needing 1L of coolant. Can you bring it...

Trans Fluid Level

OK

Power Steering Level

OK

WALK AROUND

1 flagged, 80%

Emergency Door Operation

OK

Tires and Wheel Lugs

At Risk

Flat tire. Needs replacement.



Photo 1

Glass and Mirrors

OK

Exhaust System

OK

Fluid Leaks

OK

INTERIOR/PRE-IGNITION

1 flagged, 1 action, 80%

Fire Extinguisher

At Risk

Missing fire extinguisher

To Do | Assignee SafetyCulture Staff | Priority Low | Due 03.05.2023 13:11 PST | Created by SafetyCulture Staff

Hi Jack, we have a missing fire extinguisher. Please replace.

Fuses and Reflectors

OK

First Aid Kit Complete

OK

Mirror and Seat Adjustment

OK

Seat Belt and Seat Condition

OK

START ENGINE

2 flagged, 1 action, 92.59%

Vacuum/ Air Pressure/ Oil Press

OK

Warning Buzzers/ Brakes /Emerg

OK

Amp Gauge

OK

Temp Gauge

OK

Fuel Gauge

OK

W/ S Wipers and Washers

OK

Headlights-Dimmer-Hi/ Lo

At Risk

Busted right headlight.

To Do | Assignee SafetyCulture Staff | Priority Low | Due 03.05.2023 13:12 PST | Created by SafetyCulture Staff

Hi Joe, please replace busted lights

Tail Lights

OK

Brake Lights

OK

Directional Lights

OK

Hazard Lights

OK

Overhead Red Lights

OK

Overhead Amber Lights

OK

Clearance Lamps

OK

Dash Lights	OK
Park Brake	OK
Service Brake Check	OK
Clutch	OK
Heaters/ Defrosters	OK
Horn	OK
Cleanliness	OK

Please note the added amount (if applicable) for the following items:

Fuel Added (gals)	OK
Oil Added (qts)	OK
Coolant Added (qts)	At Risk
added 1.5 qts	
P/ S Fluid Added (pts)	OK
Trans Fluid Added (pts)	OK
W/ S Washer Fluid Added	OK

Completion

Recommendations

- Do not use this school bus until front tire has been replaced
- Add coolant and monitor if there are traces of leaks
- Replace busted lights
- Follow up requested fire extinguisher

Person in Charge (Full Name and Signature)



Joanne Ybell
26.04.2023 13:13 PST

Media summary



Photo 1