

# Scissor Lift Safety Checklist

GS3205-75407 / Ge 2023 / Larry Hopkir		532 / 22 May			Complete
Score	79.31%	Flagged items	6	Actions	2
Site conducted					Unanswered
Model Number					Genie GS-2032/2632
Serial Number					GS3205-75407
Conducted on					22.05.2023 15:00 PST
Inspected by					Larry Hopkins
Location				(37.6	Pleasant, KS, USA 5156909, -97.1144039)

# Flagged items & Actions

## Flagged items

Inspection / Operating and Emergency Controls

### Steering and components are operating properly

The steering wheel can't turn right but the left turn works fine. The hyd fluid was at the add level and I topped it off.

### Inspection / Personal Protective Devices

### Housekeeping is observed in platform floor

There are still several debris left on the platform

Pothole guard is stuck

Inspection / Personal Protective Devices

**Inspection / Personal Protective Devices** 

Fire extinguishers are in place and inspected regularly

Pothole protection is in proper working condition

Fire extinguisher in place is close to expiry

To Do | Assignee SafetyCulture Staff | Priority Low | Due 29.05.2023 18:51 PST | Created by S afetyCulture Staff

Please inspect all extinguishers in place, replace them if needed.

#### Inspection / Battery, Cable and Wiring Harness

#### Check if in good working condition

Scissor lift has new battery but appears to be dismal. It could be poor battery maintenance, will have to check maintenance records to confirm.

To Do	Assignee SafetyCulture Staff	T	Priority Low	L	Due 29.05.2023 18:52 PST	Created by S
afetyCul	ture Staff		-			-

Check battery maintenance record.

Inspection / Battery, Cable and Wiring Harness

Free of excessive dirt, grease or foreign matter

vices

Needs Attenton

Needs Attenton

Needs Attenton

6 flagged, 2 actions

6 flagged, 2 actions

Needs Attenton

Needs Attenton

Dhate 1

Photo 1

Needs Attenton

#### Other actions

0 actions

100%

# **Operating and Emergency Controls**

Inspection

#### Steering and components are operating properly

The steering wheel can't turn right but the left turn works fine. The hyd fluid was at the add level and I topped it off.

Check booms and cylinder for proper working order	ОК
Check if operating and emergency controls are free of: excessive dirt, grease or foreign matter	ОК
Safety Devices	100%
Run light operates properly	ОК
Personal Protective Devices	3 flagged, 1 action, 40%
Hard hat, safety glasses, steel toe boots, harness, and lanyard are worn (if required)	ОК
Platform floor is in good order	ОК
Housekeeping is observed in platform floor	Needs Attenton
There are still several debris left on the platform	
Photo 1	
Pothole protection is in proper working condition	Needs Attenton
Pothole guard is stuck	
Fire extinguishers are in place and inspected regularly	Needs Attenton
Fire extinguisher in place is close to expiry	
To Do   Assignee SafetyCulture Staff   Priority Low   Due 29.05 afetyCulture Staff	2023 18:51 PST   Created by S
Please inspect all extinguishers in place, replace them if needed	

Please inspect all extinguishers in place, replace them if needed.

## **Tires and Wheels**

6 flagged, 2 actions, 79.31%

1 flagged, 66.67%

Needs Attenton

#### Tires are free of excessive wear, cuts, and proper inflation

OK



Photo 2			
Wheels are free of cracks and damage (bent rims, etc.)	ОК		
Lug nuts installed and secured	ОК		
Air, Hydraulic and Fuel System Leaks	100%		
Check for leaks, hose chafing and cracking, kinking or binding.	ОК		
Check for proper service levels	ОК		
Loose or Missing Parts	100%		
Check for loose or missing parts at the boom, assemblies and platform	ОК		
Battery, Cable and Wiring Harness	2 flagged, 1 action, 50%		
Check for proper installation	ОК		
Check if in good working condition	Needs Attenton		
Scissor lift has new battery but appears to be dismal. It could be po have to check maintenance records to confirm.	or battery maintenance, will		
To Do   Assignee SafetyCulture Staff   Priority Low   Due 29.05 afetyCulture Staff	.2023 18:52 PST   Created by S		
Check battery maintenance record.			
Free of excessive dirt, grease or foreign matter	Needs Attenton		
Found dirt build up on batteries			
Free of loose wire connectors, damaged electrical cables, chafing, kinking or binding of electrical cables or wires	ОК		
Placards, Warning, Control Marking and Operating Manual	100%		
Capacity label is legible	ОК		
apacity label is legible	ОК		

5/7

All warning and equipment control markings for proper operation is legible and attached	ОК	
Operating and Responsibilities Manuals are installed on the lift and are legible	ОК	
Manuals are stored in a weatherproof container and the container is easily identifiable	ОК	
Guardrail System		100%
Check for cracked welds, cracked metal, distorted components, broken structures, sign of metal fatigue	ОК	
Lanyard attachment points are in good condition	ОК	
Lanyard attachment points are near the bottom of the basket in the corners	ОК	
<b>Equipment Task Function Operation</b>		100%
Lower controls operate properly	ОК	
Platform controls operate properly	ОК	
Hazards		100%
No signs of hazards such as: drop off, holes, bumps, debris, overhead obstructions, high voltage areas or over headlines, high winds or bad weather, inadequate ground support, inadequate ventilation, hazardous atmosphere, other	ОК	
Completion		

I am ruling this scissor lift as not fit for operation. This unit should be lined up for maintenance fixes.

## Inspection Completed By

Chart Larry Hopkins 22.05.2023 18:54 PST

6/7

## Media summary



Photo 1



Photo 2