



Fire Prevention Inspection Checklist

Complete

Score	17 / 18 (94.44%)	Flagged items	1	Actions	0
Document No.					20231212
Audit Title	Office Monthly Fire Inspection (December 2023)				
Client / Site	Unionpay				
Conducted on					20.02.2024 12:38 PST
Prepared by					Verona Johnson
Location					1349 Chorro St, San Luis Obispo, California, 93401
Personnel	Verona Johnson				

Flagged items

1 flagged

Audit / Fire Prevention

The storage of materials within the work structure is setup in a way that minimizes the spread of fire within a given structure?

No

Pile of flammable logs are temporarily placed in the storage. These are to be taken care of and removed by this weekend.

Audit

1 flagged, 17 / 18 (94.44%)

Material from this audit is an interpretation of Fire Safety and Prevention Guidelines per OSHA regulations. The checklist was modeled from industry guidelines laid out on: <http://www.isri.org/docs/default-source/osha-safety/fire-protection-and-prevention-for-construction-cklst.doc?sfvrsn=2>

Fire Code Requirements

9 / 9 (100%)

Worksites equipped with firefighting material at all times?

Yes



Photo 1

Firefighting material located in prominent, easily noticeable area?

Yes

Firefighting materials are all stocked and located in convenient hallways

Indicate on floor plan below where each of the firefighting material is located.

Photo 2

Firefighting equipment is inspected per state/local mandates?

Yes

All equipment including extinguishers are inspected and monitored on a bi-monthly basis.

Indicate last inspection date/time

02.12.2023 16:00 PST

Firefighting equipment appears recently updated and in working order?

Yes

[Firefighting Equipment Inspection Log.pdf](#)

Extinguisher meets one of the following criteria:
 (i) no less than 2A rating
 (ii) 55-gallon open drum of water with at least 2 fire buckets provided per 3,000 sq. ft. of building area

Yes

Distance to reach fire extinguishing equipment (extinguisher or gallon drum) is no more than 100 feet away?

Yes

Extinguishers with a rating of 2A or greater are available on

Yes

each floor of the building?	
Is there at least one fire extinguisher next to the stairwell?	Yes
Is firefighting material kept out of freezing conditions of 0 degrees Celsius or 32 degrees Fahrenheit?	Yes
Are there more than 5 gallons of flammable or combustible liquids, or 5 pounds of flammable gas present?	No flammable materials present
Fire Prevention	1 flagged, 8 / 9 (88.89%)
Exhausts from engine powered equipment are reasonable distance from explosive material?	Yes
In the event that engine exhausts are piped outside of the worksite structure, is piping at least 6 inches away from the explosive material?	Yes
If explosive materials are piled, are piles lower than 20 feet?	Yes
Is the lawn reasonably kept with periodic, scheduled work-yard cleanup in place?	Yes
Explosive materials that are stored outdoors are at least 10 feet from the structure or indoor worksite?	Yes
The storage of materials DOES NOT block any exits within indoor working structures? Answer YES if exits are open Answer NO if any exits are blocked by stored material	Yes
The storage of materials within the work structure is setup in a way that minimizes the spread of fire within a given structure? Pile of flammable logs are temporarily placed in the storage. These are to be taken care of and removed by this weekend.	No
Is there enough space between heat-producing objects (lightbulbs, heating units)?	Yes
Are construction supplies kept at least 36 inches away from the open range of the fire door?	Yes

Media summary



Photo 1




Photo 2

File summary

[Firefighting Equipment Inspection Log.pdf](#)