

Excavator Inspection Checklist

15 Mar 2024 / Reid Tromp

Complete

Score	9 / 11 (81.82%)	Flagged items	1	Actions	1
Site conduc	ted			Marked as 'my	site is not listed here'
Conducted on				15.0	3.2024 08:20 PST
Prepared by	y				Reid Tromp
Location			1401 Wall <i>A</i>	ve, Ogden, Utah	
Excavator I	D No.				20194877

Flagged items & Actions

1 flagged, 1 action

Flagged items

1 flagged, 1 action

Engine and Cooling System

No humming or vibration when you start the engine?

No

very minimal humming heard

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 15.03.2024 12:00 PST | Created by: SafetyCulture Staff

very minimal humming heard

Call Gary from the maintenance team for additional checks

Other actions 0 actions

Structural Components

1 / 2 (50%)

No cracks, welds, or signs of damage on the frame?

No

prominent scratches found



Photo 1

No wear and misalignment in boom, arm, and bucket?

Yes

Hydraulic System	2 / 2 (100%)
Hydraulic fluid level within the recommended range?	Yes
No any leaks or damages to hoses, fittings, and cylinders?	Yes

Engine and Cooling System	1 flagged, 1 action, 2 / 3 (66.67%)			
Engine oil level within the recommended range?	Yes			
No humming or vibration when you start the engine?	No			
very minimal humming heard				
To do Assignee: SafetyCulture Staff Priority: Low Due: 15.03.2024 12:00 PST Created by: SafetyCulture Staff				
very minimal humming heard				
Call Gary from the maintenance team for additional checks				
No leaks or wear in the radiator, hoses, or belts?	Yes			

Electrical System	2 / 2 (100%)
Working lights, gauges, and switches?	Yes
No damaged wiring or loose connection?	Yes

Undercarriage	2 / 2 (100%)
Proper tracks tension?	Yes
No wears in rollers, idlers, and sprockets?	Yes

Sign-Off

Name

Reid Tromp

Reid Tromp 14.05.2024 08:28 PST

Media summary



Photo 1