

Laser Safety Checklist

LASR Enterprises, Inc. / Hazel Quintose / 21 Jun 2023

Flagged items4Actions2Facility NameLASR Enterprises, Inc.Facility Address33408 Buckeye Ln, Wilder, TN
38589, USA
(36.3333473,
-85.02747219999999)Inspected byHazel QuintoseConducted on21 Jun 2023 07:58 PST

Complete

Table of Contents

Flagged items & Actions	3
Laser Safety Checklist	4
Personal Protective Equipment	4
Housekeeping	4
Electrical	5
Machine Guarding	5
Other Hazards	5
Sign Off	5
Media summary	6



Photo 3

To do | Assignee: SafetyCulture Staff | Priority: High | Due: 28 Jun 2023 08:00 PST | Created by: SafetyCulture Staff

Undergo refresher training for operating laser cutting equipment

Laser Safety Checklist / Housekeeping

Is work area organized, free of clutter, and trip hazards?

I talked to the worker in this area, and he cleaned it just now.




Photo 4

Other actions

0 actions

No



I talked to the worker in this area, and he cleaned it just now.



Are walk areas clear?	Yes
Are blow-off air tool nozzles less than 20 psi?	Yes
Electrical	
Are extension cords free of cuts, abrasions, exposed wiring, or other hazards?	Yes
Are ground pins located on extension cords?	Yes
Are locks and tags used to lockout / tagout machines under service or repair?	Not Applicable
Machine Guarding	
Are gears, pulleys, and other moving parts covered with machine guards, cabinets, covers, chains, and sensors?	Not Applicable
Other Hazards	
Are oxygen and flammable cylinders stored more than 20 feet apart and secured?	Yes
Is work area free of other hazards?	Yes
Sign Off	

Additional Observations

Employees should wear appropriate PPE. Laser safety should not be taken lightly. Better to be safe than sorry.

Laser Safety Officer Name & Signature

Hazel Quintose 21 Jun 2023 08:01 PST

Media summary



rayjet

Photo 1

Photo 3



Photo 2



Photo 4