



Aircraft Assessment Aviation Checklist

Clark Airport / 4 May 2023 / Joan Tan

Complete

Score	83.33%	Flagged items	1	Actions	1
Site conducted					Unanswered
Airport Name					Clark Airport
Airport Classification					Commercial services
Aircrafts Parking Area On Airport					10
Conducted on					04.05.2023 15:31 PST
Prepared by (Full Name)					Joan Tan
Location					Concepcion, Tarlac, Philippines (15.3230428, 120.6523622)

Flagged items & Actions

1 flagged, 1 action

Flagged items

1 flagged, 1 action

Audit / Aircraft / Aircraft 2

Is Aircraft Air-worthy?

No

Interior damage reported: loose overhead bin at row 11



Photo 2

To Do | Priority High | Due 11.05.2023 15:34 PST | Created by SafetyCulture Staff

Hi Max, Kindly check this immediately

Other actions

0 actions

Audit

1 flagged, 1 action, 83.33%

Aircraft

1 flagged, 1 action, 83.33%

Aircraft 1

100%

Aircraft Parking Spot or Tie-down

C-123

Aircraft Number

N721AF

Does Aircraft have a current HDOT Registration Decal Visible?

Yes

Does Aircraft Owner have a current Revocable Permit with AIR-PM?

Yes

Is Aircraft Air-worthy?

Yes

Aircraft Photo(s)

Photo 1

Aircraft 2

1 flagged, 1 action, 66.67%

Aircraft Parking Spot or Tie-down

D-142

Aircraft Number

N282DF

Does Aircraft have a current HDOT Registration Decal Visible?

Yes

Does Aircraft Owner have a current Revocable Permit with AIR-PM?

Yes

Is Aircraft Air-worthy?

No

Interior damage reported: loose overhead bin at row 11



Photo 2

To Do | Priority High | Due 11.05.2023 15:34 PST | Created by SafetyCulture Staff

Hi Max, Kindly check this immediately

Aircraft Photo(s)



Photo 3

Completion

Observations and Recommendations

Fix the overhead bin of aircraft N282DF. Do not allow to fly.

Sign-off (Full Name and Signature)

A handwritten signature in black ink, appearing to be 'Joan Tan', written in a cursive style.

Joan Tan
04.05.2023 15:35 PST

Media summary



Photo 1



Photo 2



Photo 3