



Building Audit

Complete

Score	0%	Flagged items	0	Actions	1
Document No.					0048501
Audit Title					
Client / Site					
Conducted on					01.06.2023 16:16 PST
Prepared by					Brunella Nefes
Location					Alaska, USA (63.588753, -154.4930619)
Personnel					
Yoshie Dipali Neeltje Caecilia Maksim Margareta Kateřina Franjo					

Actions

1 action

Audit / Roof Structure

Screws and fixings

Poor

Some screws on the emergency exit are loose.



Photo 1

To Do | Priority High | Due 08.06.2023 16:52 PST | Created by SafetyCulture Staff

Fix screws on emergency exit ASAP

Audit	1 action
--------------	----------

Roof Structure

1 action

Beams	Good
Trusses	Good
Roof ventilation	Average
Translucent Skylight	Good
Guttering	Good
Valleys	Not Applicable
Cladding	Good
Screws and fixings	Poor

Some screws on the emergency exit are loose.



Photo 1

To Do | Priority High | Due 08.06.2023 16:52 PST | Created by SafetyCulture Staff

Fix screws on emergency exit ASAP

Ridge capping	Good
----------------------	------

Fascias

Soffit	Good
Gable	Good

External

Walls	Good
Door Frames	Average
Doors	Good
Windows	Good

Roller doors	Not Applicable
Tree interference	Not Applicable
No trees nearby	
Rubbish	Good
Fly / Vermin Screens	Good
Security Screens	Good
Down pipes	Good
Internal	
Roof sheeting (underside)	Good
Ceiling	Good
Walls	Good
Wall Tiling	Good
Doors	Good
Door Hardware	Good
Signage	Good
Floor surface	Good
Electrical	
External lighting	Good
Internal lighting	Good
Emergency lighting / exit signage	Good
Ceiling fans	Good
Power Outlets	Good
Security system	Good
CCTV System	Good
Switchboards	Good

Metering Panels	Good
Public Address	Good
Plumbing	
Tapware	Good
Hand basins	Good
Showers	Not Applicable
Cleaners Sink	Good
Hot water system	Good
Drainage	Good
Toilets	Good
PWD Toilets	Good
Urinals	Good
Furnishes & Accessories	
Fixed seating	Good
Clothes hooks	Good
Toilet roll holders	Good

Media summary



Photo 1