



# Emergency Lighting and Exit Sign Inspection Checklist

Joe and Jack Incorporation / 5 May 2023 / John James Marz

Complete

Score	<b>83.33%</b>	Flagged items	<b>2</b>	Actions	<b>0</b>
<b>Client</b>	Joe and Jack Incorporation				
<b>Conducted on (Date and Time)</b>	05.05.2023 08:55 PST				
<b>Inspected by</b>	John James Marz				
<b>Address</b>	Manor Grove Farm, 811 Undergrowth Way, Moffat US2 9EI, UK				

**Flagged items**

2 flagged

Audit / Emergency Light Checks / Emergency Light / Emergency Light 1

**Test results: Battery**

Needs Action

Faulty battery indicator



Photo 1

---

Audit / Emergency Light Checks / Emergency Light / Emergency Light 1

**Overall Assessment**

Fail

**Audit** 2 flagged, 83.33%

**Emergency Light Checks** 2 flagged, 83.33%

Emergency light inspection? Click "Add"

**Emergency Light** 2 flagged, 83.33%

**Emergency Light 1** 2 flagged, 66.67%

**Time on** 01:00 PST

**Emergency light reference number** EL-12345

**Emergency light location** Conference Room 1

**Test results: Physical condition of equipment** OK

**Test results: Battery** Needs Action

Faulty battery indicator




Photo 1

**Test results: luminous** OK

**Time off** 01:05 PST

**Overall Assessment** Fail

**Emergency Light 2** 100%

**Time on** 01:30 PST

**Emergency light reference number** EL-12347

**Emergency light location** Fire exit

**Test results: Physical condition of equipment** OK

**Test results: Battery** OK

**Test results: luminous** OK

**Time off** 01:35 PST

**Overall Assessment**

Pass

Exit sign in good working condition

---

**Completion**

---

**Recommendations**

Change faulty battery immediately

---

**Maintenance Inspector (Full Name and Signature)**



John James Marz  
05.05.2023 09:00 PST

---

## Media summary



Photo 1