

Daily End of Shift Report

5 Aug 2022 / Maurizio Carriedo					Complete
Score	0%	Flagged items	0	Actions	1
Employee Name					Maurizio Carriedo
Role				Hot	el Maintenance Staff
Team/Department					Hotel Maintenance
Date Completed					05.08.2022
Shift Schedule					9:00 AM-6:00 PM
Shift Location				(37.43	Virginia, USA 315734, -78.6568942)

Actions 1 action

Shift Report / Task Summary / Task / Task 2

Status Ongoing

To Do | Priority Low | Due 12.08.2022 14:53 PST | Created by SafetyCulture Staff

Request batteries from the Inventory team.

Shift Report 1 action

Responsibilities

Performing maintenance checks, repairs, and installation for electrical, lighting, and HVAC equipment

Task Summary

1 action

Task 1 action

Task 1

Task Description

Lighting

- Install LED lights, lamps, and bulbs on the rooms on the 2nd-5th floors.
- Inspect the interior and exterior lighting around the hotel premises.

Status Completed

Photo/Video of Task





Photo 1

Photo 2

Task 2

Task Description

Electrical

- Check if electrical wires and cables are in good condition.
- Change the batteries of the smoke detectors in the 6th-floor hallway.

Status Ongoing

To Do | Priority Low | Due 12.08.2022 14:53 PST | Created by SafetyCulture Staff

Request batteries from the Inventory team.

Photo/Video of Task



Photo 3

Task 3

Task Description

HVAC

- Inspect HVAC controls and equipment if functioning or not.Clean air intake and filters.

Status

Photo/Video of Task

Completion

Additional Notes/Observations

Reach out to the Inventory team for extra batteries for smoke detectors.

Employee Name and Signature

M. barnels

Maurizio Carriedo 05.08.2022 14:54 PST

Supervisor Name and Signature

Terenzo Vargas

Terenzo Vargas 05.08.2022 14:54 PST

Appendix



Photo 1




Photo 3



Photo 2