

Fire Marshal Inspection Checklist for Business

Building A (multi-purpose occupancy) / 27 Feb 2023 / Marc Abbey

Complete

2023 / Marc Abbey					Complete
Score	96.23%	Flagged items	2	Actions	0
Facility Name				Building	g A (multi-purpose occupancy)
Facility Owner/Mana	ged by				RealTea Inc.
Facility Contact emai	l/phone			real.tea.inc@	realteabuilding.co m
Inspection Date and	Гime			27.	02.2023 15:30 PST
Inspected by					Marc Abbey
Address					E Second St Long Beach Alamitos Beach CA 90802 United States

Flagged items 2 flagged

Fire Marshal Inspection Checklist for Business / Emergency Lights

In Good Condition

No

One emergency light is blinking when tested.



Photo 2

Fire Marshal Inspection Checklist for Business / Operating Features

Employees Trained in Fire Extinguisher Use



A new employee that had completed new hire training didn't do fire extinguisher training.

Fire Marshal Inspection Checklist for Business

2 flagged, 96.23%

Occupancy

Any Changes from Last Inspection

Yes

New storage room near the old fire exit



Photo 1

Occupant Load	100
Egress Capacity	170
Any Renovations	Yes
Only one. The new storage room.	
High Rise	No
Windowless	No
Underground	No

Building Services

100%

Utilities	Electricity
	Gas
	Water
Utilities in Good Working Order	Yes
Elevators	Yes
Fire Service Control	Yes
Elevator Recall	Yes
Heating System Type	Electric
Heating System In Good Working Order	Yes
Emergency Generator	Yes

Size	24 kw
Last Date Tested	27.01.2023
Date of Last Full Load Test	27.01.2023
In Automatic Position	Yes
Fire Pump	Yes
Date Last Tested	27.01.2023
In Automatic Position	Yes
Emergency Lights	1 flagged, 75%
Operable	Yes
Tested Monthly	Yes
In Good Condition	No

One emergency light is blinking when tested.



Photo 2

Emergency lighting appears to be adequate for the facility	Yes
Exit Signs	100%
Illuminated	Yes
Readily Visible	Yes
Photo 3	

Fire Alarm	100%
Fire Alarm Installed	Yes

Location of Panel

Cc			

Coverage	Total
Monitored	Yes

Method

Manual monthly monitoring

• Fire Department Notification	Yes
Type of Initiation Devices	Smoke
Date of Last Test	27.11.2022
Inspection Date Current	Yes
Fire alarm system is operational	Yes

Fire Extinguishers

100%

Proper Type for Hazard Protected	Yes
Mounted Properly	Yes
Inspection Date Current	Yes
Serviced and adequate in number	Yes

Hazardous Areas

100%

Protected by	Fire-Resistance Rated Separation	
	Extinguishing System	
Doors have Self-Closers	Yes	
Residential Separated	Yes	
1-Hour Fire-Resistance Rating	Yes	
Fire sprinkler system(s) is operational	Yes	
Parking Structure Separated	Yes	

Housekeeping

100%

Areas Free of Excessive Combustibles	Yes
Smoking Regulated	Yes
It's a strictly no smoking facility	
Housekeeping/storage practices are acceptable	Yes
Means of Egress	100%
Readily Visible	Yes
Clear and Unobstructed	Yes
Two Remote Exits Available	Yes
• Travel Distance within Limits	Yes
Common Path of Travel within Limits	Yes
• Dead-Ends within Limits	Yes
Adequate Illumination	Yes
All Exit Enclosures Free of Storage	Yes
Doors Swing in the Direction of Egress Travel (where required)	Yes
• Panic/Fire Exit Hardware Operable	Yes
• Doors Open Easily	Yes
• Self-Closers Operable	Yes
• Doors Closed or Held Open with Automatic Closers	Yes
Corridors and Aisles of Sufficient Size	Yes
Stairwell Allows Re-Entry	Yes
Mezzanines	Yes
Proper Exits	Yes
Exit doors are unlocked	Yes
Operating Features	1 flagged, 75%
Employees Trained in Fire Extinguisher Use	No

A new employee that had completed new hire training didn't do fire extinguisher training.

Fire Drills Conducted	Yes
• Date of Last Fire Drill	27.01.2023
Records Protected	Yes
Hydrants are operational	Yes

COMPLETION

Comments/Recommendations

Aside from the one defective emergency light and the new employee that is yet to be trained for fire safety, all is compliant. Scheduled a training session with the employee for this afternoon. The defective emergency light is being replaced as I complete this report.

Fire Marshal Name and Signature

Marc Abbey 27.02.2023 16:00 PST

Appendix







Photo 3

