



## OSHA 300 Log

000002 / Kennard Sif / 23 May 2023 / GraYellow Inc. / Caridad Teodor

**Complete**

Score	<b>0%</b>	Flagged items	<b>0</b>	Actions	<b>1</b>
-------	-----------	---------------	----------	---------	----------

**Case No.**

000002

**Employee Name (Optional)**

Kennard Sif

**Establishment name**

GraYellow Inc.

**Conducted on**

23.05.2023 11:04 PST

**Prepared by**

Caridad Teodor

## Actions

1 action

Audit / Completion

### Observations and comments

Maintenance on all assembly line machines needed ASAP.

To Do | Priority High | Due 30.05.2023 11:49 PST | Created by SafetyCulture Staff

Conduct maintenance inspection on assembly machines

Audit

1 action

## Log of Work-Related Injuries and Illnesses

### Job title

Floor Supervisor

### Date of injury or onset of illness

19.05.2023 07:30 PST

### Where the event occurred

Production floor: Assembly section

### Type of incident

Injury

### Describe injury or illness, parts of body affected, and object/substance that directly injured or made person ill.

Kennard Sif's nose was broken after an assembly line machine suddenly broke down. One of the broken parts hit his face.

### Upload photos of incident

No photo available since it happened too fast

### Classify the case. Check only one box for each case based on the most serious outcome for that case:

Days away from work

### No. of days the injured or ill worker was away from work

Employee is still currently off work. Was prescribed 2 weeks off.

## Completion

1 action


### Observations and comments

Maintenance on all assembly line machines needed ASAP.

To Do | Priority High | Due 30.05.2023 11:49 PST | Created by SafetyCulture Staff

Conduct maintenance inspection on assembly machines

### Full Name and Signature of Record Keeper



Caridad Teodor  
23.05.2023 11:50 PST