



Trailer Inspection Form

21 Jun 2023 / Ben McCross

Complete

Score	100%	Flagged items	0	Actions	0
Site conducted					Unanswered
Truck #					567
Trailer #					345
Conducted on					21.06.2023 10:57 PST
Location					I-35, Laredo, TX 78045, USA
Prepared by					Ben McCross

Inspection

100%

Pre-trip Trailer Inspection Checklist

100%

Wheel bearing play within acceptable limits

OK

Tires and wheels in good condition

Repaired

1 right front wheel replaced with the spare



Photo 1

Lug nuts tight

OK

Lights operational

OK

Trailer brake operation satisfactory

OK

Fenders and mud flaps, if equipped, secure and undamaged

OK

Springs and shackles in good condition

OK

Trailer floor undamaged

OK

Safety chains in good condition

OK

Warning equipment, e.g., reflective triangles, in the vehicle or trailer

OK

Chassis

100%

Frame

OK

Axle beam

OK

Springs

OK

U bolts

OK

Shackles

OK

Wheel bearings repacked

OK

Hub bolts

OK

Wheels	OK
Tires	Repaired
Trailer hitch	OK
Safety chain	OK
Lights	100%
Clearance	OK
Stop and taillights	OK
Turn signals	OK
Electric Brakes	100%
Lining	OK
Shoe adjustment	OK
Backing plate bolts	OK
Drum condition	OK
Electromagnet	OK
Armature disc	OK
Wiring	OK
Terminals	OK
Connection plug	OK
Brake Controls	100%
Electric controller unit	OK
Proper voltage	OK
Connector plug	OK
Wiring	OK
Manual brake controls	OK

Completion

Name and Signature



Ben McCross
21.06.2023 12:52 PST

Media summary



Photo 1