



Vehicle Pre-Start Inspection Checklist

Complete

Score	12 / 13 (92.31%)	Flagged items	0	Actions	1
-------	------------------	---------------	---	---------	---

Vehicle Make & Model

The vehicle under inspection is a Toyota Camry, identifiable by its silver color and the model year 2022.

Site

SLZ Logistics Hub

Conducted on

17.08.2023 14:00 PST

Prepared by

Macy Hopkins

Location

Queens, NY, USA
(40.7282239, -73.7948516)

Actions

1 action

Audit / Safety

WINDSCREEN: Damage Free and Screen Wash Level

Non-Compliant

The windscreen is non-compliant due to visible cracks. These obviously exceed the permissible size, compromising the structural integrity of the windscreen and obstructing the driver's field of vision.



Photo 1

To do | Assignee SafetyCulture Staff | Priority Low | Due 24.08.2023 14:05 PST | Created by SafetyCulture Staff

Replace windscreen.

Audit

1 action, 12 / 13 (92.31%)

Instructions

1. Answer "Compliant", "Non-Compliant" or "N/A" for the questions below.
2. Add photos and notes.
3. To add a Corrective Measure, click "Action", provide a description, assign it to a member, and set a due date.
4. Complete the audit by providing a digital signature.
5. Share your report by exporting it as PDF, Word, Excel, or Weblink.

Vehicle Information

Fuel Type

The vehicle is powered by petrol as its fuel source.

Height of Vehicle Unladen

1.55 meters

Max. Payload

500 kg

Choose the day of the week:

Thursday

Safety

1 action, 6 / 7 (85.71%)

WINDSCREEN: Damage Free and Screen Wash Level

Non-Compliant

The windscreen is non-compliant due to visible cracks. These obviously exceed the permissible size, compromising the structural integrity of the windscreen and obstructing the driver's field of vision.



Photo 1

To do | Assignee SafetyCulture Staff | Priority Low | Due 24.08.2023 14:05 PST | Created by SafetyCulture Staff

Replace windscreen.

OIL: Check Engine Oil & Brake Fluid Levels

Compliant

LIGHTS: Check taillights / indicators / headlight / interior

Compliant

SEATBELTS: Check all in good condition

Compliant

JACK: Check wheel brace in the vehicle

Compliant

FIRE EXTINGUISHER: Must be in vehicle

Compliant

FIRST AID KIT: Must be in vehicle

Compliant

Equipment

1 / 1 (100%)

TYRES: Check Condition and Pressure (PSI written on side of tyres)

Compliant

TROLLEY - Is there a trolley in the vehicle?

N/A

SCALES - Are scales in the vehicle?

N/A

No. of crates In

The vehicle has 15 crates inside, meeting the expected quantity for transport.

No. of crates out

The vehicle has 12 crates outside, matching the recorded quantity.

External Bodywork

1 / 1 (100%)

Check external bodywork for any new scratches, dints etc.

Compliant

Cleaning

3 / 3 (100%)

CABIN: Clean Daily

Compliant

FRIDGE: Clean Daily

Compliant

EXTERIOR: Clean Weekly

Compliant

Fuel

1 / 1 (100%)

Must be a minimum of 3/4 full. (Do not wait until end of day)

Compliant

Completion

Signature



Macy Hopkins
17.08.2023 14:12 PST

Media summary



Photo 1