



Near Miss Report Form

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0
Site conducted					Unanswered
Incident Report No.					000002
Conducted on					27.06.2023 13:45 PST
Employee Name (optional):					Lilly Singer

Audit

Instructions:

1. Required to be completed when you experience a Safety Near Miss in the workplace
2. To be completed in full and emailed to direct manager or the Health & Safety Manager.

Near Miss Defined

OSHA and the National Safety Council defines a near miss as an "unplanned event that did not result in injury, illness or damage – but had the potential to do so."

Date & Time of Near Miss:

27.06.2023 15:00 PST

Location of Near Miss. If customer site, please provide address

9 Malta St, Fairfield East NSW
2165, Australia
(-33.8745045, 150.9808365)

Select the category the near-miss most relates to:

Electric Shock

Describe how the Near Miss occurred (include the body part and type of pain):

Right hand of Dean Sammy got electrocuted while using the drill.

Describe what lead up to and caused the Near Miss. Identify root causes:

The cable appears to be damaged.

What was learned and changed due to the Near Miss?

The drill was kept aside

Photo/s that can help explain the what, where, why, or the possible injury:



Photo 1

Name and Signature (optional)



27.06.2023 16:05 PST

Media summary



Photo 1