



# Fresno Yosemite International Airport - Airport Inspection Report

Complete

<b>Score</b>	0 / 0 (0%)	<b>Flagged items</b>	0	<b>Actions</b>	0
--------------	------------	----------------------	---	----------------	---

**Document No.**

2024012542

---

## Airport Inspection Report

City of Fresno - Airports Department  
 4995 E. Clinton Way  
 Fresno, CA, 93727-1525

Tel: (559) 621-4500



**FRESNO YOSEMITE**  
 INTERNATIONAL AIRPORT

### Pavement

#### Runway Discrepancy

Safe



Photo 1

#### Taxiway Discrepancy

Safe

#### Apron Discrepancy

Safe

### Lighting

#### Runway Discrepancy

At Risk

Gate 3 is inaccessible due to Lighting that needs to be replaced.

#### Corrective action taken

Work Order

Reported

#### Taxiway Discrepancy

Safe

#### Beacon, Apron Obst. Discrepancy

Safe

### Markings

#### Runway Discrepancy

Safe

#### Taxiway Discrepancy

Safe

#### Apron Discrepancy

Safe

Visual Aids,NAVAIDs, VASI/ PAPI, REIL/ILS/ASR

**Visual Aids, NAVAIDs, PAPI, REIL/ILS/ASR Discrepancy**

Safe

Runway & Taxiway Safety Area

**Runway & Taxiway Safety Area Discrepancy**

Safe

Runway Protection Zones

**Runway Protection Zones Discrepancy**

Safe

Wind Direction Indicators

**Wind Direction Indicators Discrepancy**

Safe

Storm Drainage System

**Storm Drainage System Discrepancy**

Safe

Signs, Gates, Fence

**Signs, Gates, Fence Discrepancy**

Safe

Wildlife Observation

**Wildlife observed?**

No

Additional Observations and Comments

**Any additional comments?**

No

Inspection Details

**Inspector Name (First & Last)**

*Wyman Cole*

Wyman Cole  
31 Mar 2024 20:59 PST

**Inspection completed at (Select Date/Time)**

26 Jan 2024 09:00 PST

Inspection Reviewed by Airport Airside Superintendent (AAS)

**AAS Name (First & Last)**

*Ciara Maggio*

Ciara Maggio  
31 Mar 2024 21:03 PST

## Media summary



Photo 1