

# **Factory Visit Report**

30 Jun 2025 / Janelle Kovacek

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	1
Prepared By					Janelle Kovacek
Location				Wa	Palmer-Wasilla Hwy, asilla, AK 99654, USA 6794, -149.4037274)
Date				3	30.06.2025 10:31 PST

**Actions** 1 action

Factory Operations & General Observations

#### **Machinery & Equipment Status**





Photo 1

To do | Priority: High | Due: 02.07.2025 12:00 PST | Created by: SafetyCulture Staff

## Fouling on the Heat Exchanger

Hi Norwich, please remove the fouling on the surface of the heat exchanger. Coordinate with the admin and procurement team should you need to replace parts. Thank you

## **Visit Overview**

# **Purpose of Visit**

	Quality Inspection	Health & Safety Audit
Visit Type		Scheduled

# **Factory Representative**

Vito Kuhlman

Vito Kuhlman 07.07.2025 10:36 PST

## **Factory Operations & General Observations**

1 action

#### **Production Areas Visited**

**Production Floor** 

Raw Material Storage

#### **Machinery & Equipment Status**





Photo 1

To do | Priority: High | Due: 02.07.2025 12:00 PST | Created by: SafetyCulture Staff

#### Fouling on the Heat Exchanger

Hi Norwich, please remove the fouling on the surface of the heat exchanger. Coordinate with the admin and procurement team should you need to replace parts. Thank you

General Cleanliness Good

No issues with general cleanliness. There's just clutter near the exit of the production area.



Photo 2

**Workflow Efficiency** 

Minor Delays

This is caused by the partially operating heat exchanger.

Safety, Compliance & Quality					
PPE Usage	Always Used				
Emergency Exits	Partially Obstructed				
Compliance with Local Regulations	Fully Compliant				
Quality Control Procedures in Place	Yes				

# **Key Observations & Recommendations**

# **Top Strengths, Areas of Concern, and Suggestions**

Please see attached file for the detailed observation and suggestion.

Factory Visit Observations and Recommendations.pdf

**Schedule of Next Visit** 

14.07.2025 09:00 PST

## Sign-off

## **Inspector's Name and Signature**

Janelle Kovacek

Janelle Kovacek 07.07.2025 10:50 PST

## **Report Reviewed By**

Janet Hickle

Janet Hickle 07.07.2025 10:51 PST

#### **Reviewer Feedback**

See my suggestions in the attached file

Factory Visit (Reviewer Feedback).pdf

# Media summary





Photo 1 Photo 2

# File summary

Factory Visit Observations and Recommendations.pdf Factory Visit (Reviewer Feedback).pdf