

CDL Pre-Trip Inspection Checklist

Class A: Tractor Semi-Trailer, Truck & Trailer, or Bus & Trailer / 8 Sep 2025 / John Reggies

Complete

Score	53 / 55 (96.36%)	Flagged items	1	Actions	2	
Inspection Class					actor Semi-Trailer, er, or Bus & Trailer	
License Plate KJ7-9					KJ7-92L	
Conducted on				08.09.2025 15:30 PST		
Prepared by				John Reggies		
Location				-	N, Chesapeake, VA 23320, USA 759, -76.2329645)	

Flagged items & Actions

1 flagged, 2 actions

Flagged items

1 flagged, 1 action

Report / Driver Approval

Is the driver satisfied with the operating condition of the vehicle before driving?



Replace service brake first before next trip

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 22.09.2025 17:11 PST | Created by: SafetyCulture Staff

Replace service brake first before next trip

Other actions 1 action

Report / In-Vehicle/Engine Start

Service brake check

service brake is damaged



Photo 1

To do | Assignee: SafetyCulture Staff | Priority: High | Due: 22.09.2025 17:09 PST | Created by: SafetyCulture Staff

Pls replace the service brake ASAP!

Inspection Checklist Type



Class A Inspection

Tractor Semi-Trailer or Truck & Trailer or Bus & Trailer



2

Class B or Class C Inspection

Straight Truck or Other Straight Vehicle



3

Class B or Class C Inspection

Passenger or School Bus



Select Inspection Class

In-Vehicle/Engine Start

performed correctly)

Class A: Tractor Semi-Trailer, Truck & Trailer, or Bus & Trailer

1 action, 8 / 9 (88.89%)

Air or hydraulic brake check (Automatic failure if not

abla

Parking & trailer (if applicable) brake check

Service brake check

 \checkmark

service brake is damaged



Photo 1

To do Assignee: SafetyCulture Staff Priority: High Due: 22.09.2025 17:09 PS by: SafetyCulture Staff	ST Created
Pls replace the service brake ASAP!	
Lighting indicators	V
Emergency equipment	V
Windshield & traffic monitoring devices	V
Wipers & washers	V
Heater & defroster	\checkmark
Horn(s)	\checkmark
Lights Operations Check	3 / 3 (100%)
All external lights	V
ABS light	V
DEF warning	V
Front of Vehicle/Engine Area	4 / 4 (100%)
Lenses	V
Fluid levels	V
Fluid & air leaks	V
Steering systems	V
Steering Axle	12 / 12 (100%)
Tires	
Steer: min 4/32 tread	V
Drive: min 2/32 tread	V
No recaps on steer axle	V

Check inflation with gauge	\checkmark
Rims	
Lug nuts	\checkmark
Springs/mounts & air bags & shocks	\bigvee
Brake lines or hoses & leaks	
No abrasions, bulges, cuts	\checkmark
No leaks	\checkmark
Brake contaminates	\checkmark
Drums/linings dry	abla
No grease, oil, or mud	
Air Brake Check (A.L.E.G.)	4 / 4 (100%)
Air loss check: ≤4 psi/min	\checkmark
Low air alarm: before 55 psi	\checkmark
Emergency brake pop-out: 20–45 psi	\checkmark
Governor cutoff: 90–140 psi	\checkmark
Side of Vehicle	5 / 5 (100%)
Lenses & reflectors	\checkmark
Traffic monitoring devices	abla
Battery	abla
Fuel tank(s)/DEF tank	\checkmark
Frame(s)	\checkmark
Combination Vehicles Only	4 / 4 (100%)
Air & electric lines & connectors	\checkmark
Fifth wheel skid plate or pintle hook or tow hitch	

Kingpin & apron & gap or drawbar ring & tongue or coupler & tongue			
Locking & safety devices	\checkmark		
Combination/5th Wheel	5 / 5 (100%)		
Check mounting bolts & platform			
No apron gap	abla		
Locking jaws secure	abla		
Release arm latched	\checkmark		
Safety pin in place	\checkmark		
Trailer Only	2 / 2 (100%)		
Landing gear & clearance			
Reflective tape	abla		
Lenses & reflectors	2 / 2 (100%)		
50% of trailer sides			
100% of trailer rear	\checkmark		
Emergency Equipment	3 / 3 (100%)		
Spare fuses			
3 reflective triangles	\checkmark		
Fire extinguisher (charged & secured)	\checkmark		
Driver Approval	1 flagged, 1 action, 1 / 2 (50%)		
Are all noted repairs completed and certified from the last post-trip inspection report?	Yes		
Is the driver satisfied with the operating condition of the vehicle before driving?	No		
Replace service brake first before next trip			
To do Assignee: SafetyCulture Staff Priority: Low Due: 22.09.2025 17:11 PST Created by: SafetyCulture Staff			

Replace service brake first before next trip

Sign Off

Prepared by

John Reggies 15.09.2025 17:11 PST

Media summary



Photo 1